

EPA/UIC INSPECTION REPORT

Inspection Type Com  
 Inspection Frequency E.O.M.  
 Violation Code H2

Inventory No. 4652  
 Authorization \_\_\_\_\_  
 Authorized to Inject \_\_\_\_\_

Company/Operator KWB Oil Property Management, Inc.  
 Business Address 15 E. 5th St. #3300 Tulsa, OK 74103  
 Individual Contacted none Title \_\_\_\_\_

Lease Name & Well (b) (9)  
 Legal Description \_\_\_\_\_

Well Information: SWD/ER, Active/TA/P&A  
 Authorized Injection: Pressure \_\_\_\_\_ Rate \_\_\_\_\_  
 Long String Casing Size 6 5/8" Tubing Size none

Report of Conditions as of this Date:

Lease: Active/Inactive Well hooked up for injection: Yes/No  
 Injecting at time of inspection: Yes/No  
 Required fittings on tubing and casing/tubing annulus: Yes/No/Not Applicable  
 Injection Pressure zero; How Determined T.A.  
 Annular Pressure ?; How Determined \_\_\_\_\_  
 Injection Rate zero; How Determined T.A.  
 Well plugged at Surface: Yes/No/Undetermined  
 Samples Taken no Photographs Taken none

Description of wellhead hookup and injection facility:

T.A. 2 3/8" tubing in hole, open at top, recent workover per log settled tracks, annulus is shut in.

RECEIVED

JAN 5 1989

EPA 6W-S  
 REGION VI

Weather Conditions and Observations clear, overcast at 12 mph, 46°F  
no sign, across up rocky bottom creek, well sits out back of  
creek.

Inspection Date 12/30/88 Time Arrived 1200 Departed 1220  
 Field Inspector Blaine Edmon  
 EPA Reviewer EL Date 1/10/89

RECEIVED  
 JAN 12 1989